
Work Instruction Number 109 - "Workforce in Road" signs (Relaxation Works) All Amberon "Traffic Management Installations or Removals on any main road or approaching road works 40mph and above" (unless the site specific risk assessment deems it necessary on lower speeds of 40mph) must display the "Workforce in road Slow" sign, this being the 1st Sign out and last sign in.
WORKFORCE IN ROAD SLOW
NO PARKING CONES TO BE PLACED OUT ALONG THE ENTIRITY OF THE DIVERSION ROUTE
TRAFFIC MANAGEMENT NOTES:
1) All temporary traffic management shall be in accordance with Chapter 8 of the Traffic Signs Manual 2009.
2) All temporary traffic management shall be in accoradance with the Traffic Signs (Ammendment) (No.2) Regulations and General Directions 2016.
3) All temporary traffic management shall conform to the Safety at Street Works and Road Works, A Code of Practice.
4) All temporary traffic management signs should be located 450mm min from the kerb face.
5) All temporary traffic mangement sign locations are indicative and are subject to on site approval from the Engineer.
Torrs Park
BROOKDALE AVENUE
OSBORNE ROAD
CHURCH ROAD
WILDER ROAD
BROOKFIELD
VICTORIA RD
PW
OAK TREE
CHURCH STREET
PO
F Sta
TORRS PARK
UPPER TORRS
TRINITY GARDENS
Diverted traffic
Diversion ends
ROAD AHEAD CLOSED
Diversion
ROAD CLOSED
HORNE ROAD
Hospl
BELMONT AVENUE
Diverted traffic
Diverted traffic
Diverted traffic
Diversion ends
ROAD AHEAD CLOSED
ROAD CLOSED
RICHMOND ROAD
COPSE
Diverted traffic
Diverted traffic
Diverted traffic
Diversion
ROAD AHEAD CLOSED
STATION ROAD
ST BRANNOCK'S PARK ROAD
PARK HILL ROAD
FURZE HILL
HILLINGTON
LANGLEIGH PARK
Key
Traffic sign
Traffic cone/cylinder
No waiting cone
Pedestrian barrier
Road closure
Diversion route
N
Checked by: DAVE MOORE
Customer: WALES & WEST
Job Reference: 3001603185
Location: Station Road, Ilfracombe, EX34 8DE
Date: 15/09/2022
Description: Road Closure + Diversion
Scale: NTS
Amberon Ltd
Tel: 0845 371 5050
Produced By: JOSH HARPER
Drawing Ref: 15/09/2022 - JH - 3977
This Drawing is subject to Copyright and remains the property of Amberon Ltd.
Amberon Ltd